



# RU-7

## Fast, full pneumatic end forming machine



Clamping



Forming tools



Sample

### Technical details:

Fast pneumatic " Plug and play"  
end forming machine

No electrical power supply necessary

Easy operation without complicated training

Tooling strokes individually adjustable

2 or 4 steps available

Total changeover time less than 5 minutes

Minimal lubrication system

Pneumatic drives and control feature low energy  
consumption, very little maintenance, no heat  
generation

Easy to transport due compact design without  
hydraulics and electric connections.

### Technical standard specifications:

Forming steps	1 to 4
Tooling Stroke	40mm
Forming force	max.70 kN
Clamp force	130 kN
Electrical connection	none
Repeatability	0,02 mm
Forming speed	1 Sec. per 1 Step
Cycle time	4 Steps in 6 Sec.
Tool distance	85mm
Pneumatic connection	min. 6 bar
Approx.:ca.:	1600 l/min
Dimension (LxWxH):	1400 x 900 x 2000 mm approx.
Weight	700 kg approx.

### Available options:

Tooling set  
 Clamp jaws – various clamp concepts  
 Loading systems  
 Interfacing to other machines  
 Safety devices  
 Customer specific requirements

### Rosenberger Aktiengesellschaft

Am Häuslerain 16, D-79263 Simonswald

Telefon: +49(0)7683-91900-0, Telefax: +49(0)7683-91900-29

E-mail: Info@RosenbergerAG.com www.RosenbergerAG.com